This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problems Mailbox.

THIS PAGE BLANK (USPTO)

55

80

DRAWINGS ATTACHED.



Date of Application and filing Complete Specification: July 12, 1957. No. 22216/57.

Complete Specification Published: June 21, 1961.

Index at Acceptance: -Classes 83(3), B2P1, K(2A4D: 2A4G: 2A8A: 3C7: 3E: 3F: 3G2: 3J: 3L2:3L5:3L6:5D1:5J:7B8A1:7B8A3:7B8X:7C2:7C3:7M:7P), W7C; 83(2), A(73:98); and 83(1), F11(H:J).

International Classification: -B23b, c. B22c. B23p.

COMPLETE SPECIFICATION.

Improvements in or relating to the Manufacture of Cast Worm Wheels.

I, James Albert Hatch, a Citizen of the United States of America, of 1357 Franklin Street, Detroit, Michigan, United States of America, do hereby declare the invention,
5 for which I pray that a patent may be
granted to me, and the method by which it
is to be performed, to be particularly described in and by the following statement:—

This invention relates to the manufacture 10 of cast worm wheels.

According to one aspect of the present invention there is provided apparatus for use in forming mould cavities in a mould blank for casting a worm wheel, including 15 a support for mounting said blank; first means for arcuately moving said support about a first axis corresponding to the rotational axis of a worm with which the wheel to be manufactured is to be used; second 20 means for arcuately moving said blank mounted on said support, about a second axis corresponding to the rotational axis of the wheel to be cast; and mechanism providing for simultaneous operation of said first and second means, the arrangement being such that said blank can be moved as aforesaid against cutting means to form said cavities.

According to another aspect of the present 30 invention there is provided a method of manufacturing a mould for casting a worm wheel, including the steps of forming a plurality of arcuate mould segments constituting mould blanks, forming mould 35 cavities on the concave inner surfaces of the individual segments with the aid of the apparatus defined in the preceding paragraph, so as to provide mould contours in said segments which are convex trans-40 versely to the latter and are complementary to the teeth of the worm wheel to be manu-

[Price 3s. 6d.]

Prince so so

factured; and assembling said segments to form a continuous annular mould having said contours on the inner surface thereof.

Although the present apparatus and method are suitable for use in the production of worm wheels of such accuracy as not to require substantial machining before being used for the transmission of substantial mechanical power, the said apparatus and method may also be used in the production of worm wheels which are to be machined to a required accuracy before such use. In this case the mould is constructed to provide a gear wheel of a desired oversize.

It will be apparent that the product of the method defined above will be a worm wheel having sufficient precision as to its tooth contours to be used immediately with a worm, without requiring further machining. Indeed, although a lapping operation may be performed during which a minute amount of metal is removed, this is by no means essential, since the worm wheel upon removal from the composite mould will not even shown mould marks at the lines of separation of the mould segments.

For a better understanding of the present invention and to show how the same may be carried into effect, reference will now be made to the accompanying drawings in which:-

Fig. 1 is a front side elevational view of one embodiment of a machine for forming cavities in a mould blank;

Fig. 1a is a diagrammatic fragmentary side view of certain parts of a mould segment produced by the machine;

Fig. 2 is a plan view of the machine of

Fig. 1, with certain parts omitted;
Fig. 3 is an end elevational view from the left of Fig. 1;

Price So. Od.

10

35

Fig. 4 is a fragmentary view in vertical cross section along line 4-4 in Figs. 1 and 5; Fig. 5 is a fragmentary cross sectional view taken on the line 5—5 of Fig. 4;

Fig. 6 is a cross sectional view taken on

the line 6—6 of Fig. 1;

Fig. 7 is a front elevational view of the structure of Fig. 6 looking towards the left in that figure with certain parts removed; Fig. 8 is a plan view of the structure of

9 is a fragmentary side elevational view illustrating an alternative drive arrangement for the machine;

Fig. 10 is an end elevational view from

the left of Fig. 9;

Fig. 11 is a front elevational view illustrating a mounting for a rotary cutter or tool of the apparatus;

Fig. 12 is a fragmentary sectional view taken along the line 12-12 of Fig. 11;

Fig. 13 is a fragmentary end elevational view illustrating a further alternative drive

arrangement for the machine;

Fig. 14 is a view in section on a plane normal to the axis of the assembly shown, generally illustrating the manner in which segments having mould cavities are arranged and held in a suitable retainer (not shown) in the form of a ring-like composite mould;

Fig. 15 is an end elevational view of a worm wheel cast in a mould such as is

shown in Figure 14.

Referring to Figs. 1 and 2, the dot-dash line WO represents an axis which corresponds to the rotational axis of a standard worm with which a wheel to be cast is to be used. In Fig. 2, the dot and dash line WH (further identified by a dot in Fig. 1) represents the rotational axis of the worm wheel to be cast. These axes are substantially mutually perpendicular to one another and are in that fixed relationship for any operative position of the machine.

The rotational axis of the rotary end mill cutter or tool T, in the form of apparatus illustrated, is preferably in a plane containing the worm axis WO and, in a centered condition, is represented by the mutual perpendicular to the axes WO and WH, and is preferably arranged to be angularly adjustable in this plane. For descriptive purposes, this plane will be referred to as the axial plane; it corresponds to what is commonly known as the axial plane of a worm wheel.

A finished mould segment B is shown mounted in the machine but this segment may also be considered to be an unfinished blank, i.e., lacking the machined mould cavities MC. The dotted lines generally designated by the letter l indicate the appearance of such blank. Fig. 1a is a fragmentary section of a finished segment B as taken in the axial plane and illustrates certain portions of the mould cavities MC. The letter C represents the sides or mould contours (also specially indicated by the letters C1. C2, etc., C1¹, C2¹, etc., in Figs. 1 and 2) which correspond to the sides or lead contours of the teeth of the wheel to be cast. The letter t represents the root of the cavity or the throat of the tooth to be cast. The letters MB represent a mould matrix body (corresponding to the space between teeth to be cast) with the contours C on either side thereof. The letter r represents the top of the mould body or the root between teeth to be cast. The various contours, C1, C2, etc., C1¹, C2¹, etc., can be referred to as lead contours. A contour in the axial plane (as represented by the letters C in Fig. 1a) can be referred to as the pressure angle contour.

To form the various mould cavities in the mould matrix body MB in the preferred manner, the machine provides for the blank to engage and pass by the cutter by imparting to the blank two simultaneous motions—one motion being about the axis WO (to provide an inwardly convex cut across the axial plane of the mould section) and the other about the axis point WH (to produce the desired helix form). These rotations are generally indicated by the respective arrows adjacent the axes.

A foundry mould is built-up from a plurality of arcuate segments which can be radially removed outwardly from the circumference of a gear wheel cast thereagainst. 100 The mould segments are derived by cutting a cast circular blank or appropriate cross sectional shape and thickness, the segments then being provided with mould cavities on their internal arcuate surfaces which are 105 of such shape as to produce the desired contour of the teeth of the worm wheel.

For producing a worm wheel which need not be subsequently machined, the mould cavities must be of such accuracy and pre- 110 cision as can be produced only by a close tolerance mechanical cutting of the material Thus, a cutting tool is caused to thereof. generate the precise mould form required, which will in the case of a worm wheel be 115 of convex outline from side to side across the arcuate inner surface of the mould blank segment being machined. The form takes into consideration not only the mathematically derived contours necessary for accurate 120 engagement of the cast wheel, without further machining, with a mating worm, but must also vary the precise amount from the contour of the ultimate cast teeth to allow with accuracy for the shrinkage of the metal 125 in cooling in the mould.

It is seen that by adherence to these procedures a gear wheel of sufficient accuracy may be produced to operate satisfactorily

BNSDOCID: <GB___871020A 1 >

3.

75

95

with a mating worm without further machin-

In Fig. 1 the numeral 1 indicates a base, which is mounted by means such as bolts 11-11 on a sliding table M of a standard horizontal or vertical type milling machine having mechanism for moving the table in a vertical direction and to the left or right as viewed in Fig. 1. These standard machines are ordinarily employed in the service or maintenance shop of a foundry. The blank B is mounted on a cradle generally indicated by the numeral 5 and this cradle is arranged to be rotated about the axis WO.

15

As best seen in Figs. 1 and 2, the base 1 has two uprights or supporting brackets 3 and 4, which carry the cradle 5. As best shown in Figs. 2 and 8, the cradle has a flat back portion 6, the top of which has an arcuate cut-out 7 (see also Fig. 7) and near the top at each side of the back portion are two forwardly projecting ring-like bosses or extensions 8 and 9. The extension 8 carries a shaft 10 which is rotatably mounted on the end uprights 3 and is fixed to the extension 8 by a pin 11. Shaft 10 is driven by a suitable connection to the driving mechanism of the milling machine. The extension 9 is fixed to a stub shaft 12 as by set screw 13, the shaft being rotatably mounted in the end upright 4. The rotational axes of the shafts 10 and 12 coincide with the axis WO. The shaft 10 is rotated to cause rotation of the cradle 5, hence, of the mould blank, about the axis WO in a manner to be described.

There are three forwardly projecting journal extensions 14, 15 and 16 on the bottom part of the back portion 6. The extensions carry a shaft 17 (see Fig. 1) rotatably mounted therein as by bushings 141, The shaft extends through an 15¹ and 16¹. arcuate slot 18 (see Figs. 3 and 4) in the upright 3, and when the cradle rotates about axis WO the shaft 17 moves through this slot 18. As best seen in Fig. 5, the shaft carries a spacer 19 secured thereto as by the set screw 20 (Fig. 1). A thrust bearing 21 is disposed between the spacer 19 and ex-50 tension 14 and a thrust bearing 22 is disposed between the extension 14 and a collar 23 held on the shaft as by set screw 24. Interjacent the two extensions 15 and 16 is a worm 25 which is keyed on the shaft 17 and held in axial position by the nuts 26 and 27, which are threaded on the shaft. Rotation of the shaft 17 causes the blank B to be moved about the axis WH, as will be described shortly.

As best seen in Fig. 1 and 6, the back portion 6 of the cradle carries an adapter generally indicated by the numeral 29. The adapter has a plurality of vertically extending slots 30—30 which receive the screws 31—31 threaded in the back portion 6 of

the cradle. When the screws are loosened. the adapter may be vertically adjusted with respect to the cradle. The top of the adapter is provided with an arcuate cut-out 38 which, in the particular adjusted position thereof, is in line with the arcuate cut-out 7 on the cradle (see Fig. 6). Before proceeding, it is desired to point out that the cradle and adapter may be constructed as a single unit rather than as two parts, as shown.

As best seen in Figs. 6, 7 and 8, the adapter is provided with a forwardly extending arcuately-formed portion 39 having an arcuately-formed surface 40. The center or axis of this surface 40 is coaxial with the axis WH. As will be seen from an inspection of Fig. 6, in cross section the lower or radially outermost part 41 of the blank B is generally in the form of an inverted T and has an arcuate outer surface 42 which corresponds to and abuts the surface 40, as best seen in Fig. 1. It will be apparent that if the blank is moved longitudinally along the surface 40, i.e., as viewed from left to right or vice versa as viewed in Fig. 1, the motion of the blank will be about the axis WH. The radially innermost part of blank segment B constitutes a matrix portion in which the mould tooth cavities MC are to be machined.

As best seen in Figs. 6 and 7, the upper portion of the adapter has an arcuatelyshaped lip 43 which fits over the bottom portion of the blank. The height of the blank B and the distance between the lip 100 43 and surface 40 is made whereby to provide a sliding fit for the blank. The outer end of the portion 39 of the adapter carries an arcuately-shaped guide 44, which is secured thereto as by screws 45. Fitting 105 over the guide and portion 39 is an index sector or slider 46.

As seen in Figures 1 and 6, the slider 46 carries a plurality of apertures or holes 47—47 which lie along a common arc in- 110 dicated by the dotted lines 48, the center of the arc being coaxial with the axis WH. The apertures or holes 47 are angularly spaced apart along the arc a distance corresponding to the axial angular distance be- 115 tween adjacent teeth of the wheel to be cast. As best seen in Fig. 6, the blank B has a hole 49 which lies on an arc whose center is coaxial with the axis WH. A pin 50 is inserted in the lowermost hole 47a and 120 mates with threads in the blank hole 49 as indicated in Fig. 6. On the opposite side of the blank is located another hole 51, which is coaxial with the hole 49. When the pin 50 is inserted in the holes in the 125 slider and blank, it is tightened sufficiently to firmly hold the blank B fixed with respect to the slider, yet provide a sliding fit be-tween the slider and the guide 44 and adapter 29.

As seen in Fig. 1, the lower portion of the slider 46 is provided with a gear sector 52 which meshes with the worm 25. It will be apparent that when the worm 25 is rotated (by rotation of the shaft 17), the slider will be moved and hence, move the blank B along the surface 40 or about the axis WH.

The foregoing arrangement of pin and holes not only provides engaging means between the blank and the slider whereby the blank can be moved about the axis WH, but in addition, provides a means whereby the blank can be indexed about axis WH so that the various mould cavities can be formed at the proper places on the blank. The manner of indexing will be explained later.

Referring back to worm 25 in Fig. 1, it will be recalled that the worm is keyed on 20 the shaft 27 and held in axial position by the threaded nuts 26 and 27. This arrangement permits the worm to be shifted axially on the shaft to cause movement of the slider and blank about the axis WH. For example, if the nut 27 is backed off and the nut 26 is screwed up, the worm will be shifted toward the right as viewed in Fig. 1. This adjustment is called "side feed" and is important because it provides a means for causing movement of the blank about the axis WH without any movement of the blank about the axis WO. As will be explained hereinafter, this side feeding is used in correctly setting up the blank with respect to the cutter for the cutting or forming operation. Typical drive mechanisms for effecting simultaneous motion of the blank B about the two axes will next be described.

As mentioned heretofore, rotation of shaft 10 causes the blank to be moved about the axis WO and rotation of shaft 17 causes the blank to be moved about the axis WH. There are two types of drives for effecting the rotation of said shafts shown herein. In one type, the shaft 10 is directly rotated and this rotation, acting through certain motion transfer mechanism, causes rotation of shaft 17. In the other type, the shaft 17 is directly rotated and this rotation, acting through certain motion transfer mechanism, causes rotation of shaft 10. The motion transfer mechanism will next be described.

As best seen in Figs. 1, 4 and 5, a strap 68, which is slotted as at 69, is disposed over the shaft 10. By tightening up on the screw 70, the strap is fixedly held on the shaft 10. A bushing 71 is mounted on the bottom of the strap, which provides for the shaft 17 to be rotatably movable in the strap. As will be apparent, when the shaft 10 is rotated, the strap 68 will cause the shaft 17 to move through the arcuate slot 18, or alternatively, if the shaft 17 is moved

through the slot 18, the shaft 10 will be 65 rotated.

70

75

80

85

As best seen in Figs. 3, 4 and 5, a change gear bracket 72 is mounted on the shaft 17 by a bushing 73. The bracket is slotted and may be tightened up on the bushing as by the screw 721. The mounting provides for the shaft 17 to be rotatable with respect to the bracket. The bracket is held fixed on the strap 68 by means of the lock-nut 74 threaded on the shaft 17 and further, by the screw 75 which is threaded into the strap. An arcuate slot 751 in bracket 72 provides for the angular adjustment of the bracket with respect to the axis of the shaft. gear 76 is keyed on the end of the shaft 17, being held thereon by the nut and lock washer assembly 77.

The bracket 72 has further T slots 78 and 79 carrying idler studs 80 and 81, which can be adjusted in the slots and locked in position. These T slots and studs are of standard construction and need not be described in detail. The idler studs 80 and 81 respectively carry meshing gears 82 and 87, the former of which is in mesh with gear 76. An arcuate gear sector 88 is secured to the end upright 3 as by the screws 90 and is arranged to mate with the gear 87.

From the foregoing, it will be apparent that if the shaft 17 is directly rotated, gear 87 will be caused to run along the sector 88; hence, the strap 68 will be moved and this will cause rotation of shaft 10. Note also that the shaft 17 will move through the arcuate slot 18. On the other hand, if the 100 shaft 10 is directly rotated, the strap 68 will cause the shaft 17 to move through the slot 18; and as a result the mould blank B in the cradle 6 carrying shaft 17 will be correspondingly rotated about the axis WO. 105 Since the gear 87 is meshed with the sector 88, the gear 76 will also be rotated and cause rotation of shaft 17 about its own axis.

The above-described gearing, together with worm 25 and sector 29, is arranged so 110 that the resultant compound motion of the blank follows, so to speak, the helix angle of the wheel to be cast. In other words, as the blank is rotated about the worm axis WO, it is simultaneously rotated about the 115 wheel axis WH, the two rotating developing the desired helix. A different helix angle may be obtained by changing the gear ratios.

An arrangement wherein the shaft 17 is 120 driven directly from the milling machine is shown in Figs. 9 and 10.

The base 1 is mounted on the slidable table M, which carries a shaft 92 interconnected to the driving mechanism of the 125 milling machine. A gear 93 is mounted on a shoulder on the shaft and is keyed thereto as by key 94. A collar 95 holds the gear on the shaft. As indicated in Fig. 9, the

shaft may extend outwardly and a handwheel (not shown) may be coupled thereto for manual operation in those instances where the driving mechanism for the milling machine has means for disengaging the shaft 92 from the drive.

Also mounted on the table M is a Ushaped bracket 96 which is secured thereto as by bolts 97. An adjusting arm 98 is secured to the bracket 96 as by the bolt or stud 99 and carries a stub shaft 100 on which is rotatably mounted a gear 101 held on the shaft as by the nut and washer assembly 102. This gear 101 meshes with the gear 93. Another fixed shaft 103 is threaded in the U-shaped bracket 96 and rotatably mounts the gear 104, which is held on the shaft by the nut and washer assembly 105. Near the top of the bracket is disposed a shaft 106 which is mounted in the bracket as by bushings 107, 108. Collars 109 and 110 are fixed to the shaft as by set screws 111 and 112 and operate to hold the shaft against axial movement. A gear is 25 mounted on a shoulder in the shaft 106 and is keyed thereto as by the key 114, the gear being firmly held on the shaft by the nut and washer assembly 115. This gear 113 meshes with the gear 104, which in turn meshes with gear 101 on arm 98. opposite end of the shaft 106 carries a bushing 116 on which is mounted a strap 117, in which shaft 106 rotates. A gear 118 is mounted on a shoulder on the shaft 106 and is keyed thereto by the key 119. A nut and lock washer assembly 120 holds the gear and strap on the shaft.

As indicated in Fig. 9, a coupling device 121 end-couples the shaft 17 to another shaft 122 journalled in the lower part of strap 117 by means of a bushing 123. A gear 124 is mounted on a shoulder on the shaft 122 and is keyed thereto by key 125. A nut and washer assembly 126 holds the strap 117 and gear 124 firmly on the shaft 122, with the gears 118 and 124 in mesh with one another. The shaft 122 is also sustained in a further strap 127 by means of the bushing 128, the shaft being thus rotatable in strap 127 as well as strap 117. Preferably the top of the strap 127 is slotted as indicated at 129 (Fig. 10) and is held fixed on the shaft 10 by taking up a screw 130. The arrangement of the machine to 55 the right of the coupling 121 (Fig. 9) is the same as has been previously described and need not be mentioned further.

When power is applied to the shaft 92. the gears 93, 101, 104 and 113 are rotated, which causes rotation of the shaft 106, gear 118, oear 124 and shaft 122. The rotation of shaft 122 causes the shaft 17 and the worm 25 to rotate, which causes the blank to move about the axis WH. Rotation of the shaft 17 in turn causes rotation of the shaft 10, by means of the motion transfer mechanism previously mentioned. Strap 127, being fixed on shaft 10, also aids in imparting rotation to shaft 10. However, the the prime purpose of this strap and strap 117 is to maintain center distance between respective connected shafts.

Figure 13 illustrates a modified arrangement wherein the shaft 10 is directly driven. Numbers corresponding to those used in connection with Figs. 9 and 10 are also used in Fig. 13, where the parts are the same or substantial equivalents. The gear 93 mounted on shaft 92 drives a gear 83 rotatably mounted on a stud 84. The gear 83 is a double gear including a further gear 85 which drives gear 104. The gear 104 drives gear 113 and thus, in turn, drives shaft 106, which is directly connected to shaft 10 by coupling 86. The machine to the right-hand side of the coupling (except for the size of gear 76 as noted below) is the same as has been described. Also, the effect of directly rotating shaft 10 has been described and need not be further mentioned.

The type of drive arrangement selected for use depends generally on the helix angle of the gear to be cast. The helix angle may require that the gear ratios be of a nature so that gear 76 on the shaft 17 is small or large. When the gear 76 is large cnough so that it is easily rotated by the gears 82 and 87, the arrangement of Fig. 13 is used. If the gear is small, the arrangement of Figs. 9 and 10 is used.

The drive arrangement of Figs. 9 and 10 provides an alternative means for side feeding. Note that if the gear 82 is removed from the change gear bracket 72 and the drive mechanism operated, the shaft 17 105 will be rotated; hence, the blank will be moved about the axis WH. The shaft 10 will of course, remain fixed and there will be no motion of the blank about axis WO.

The following example will illustrate the 110 gear ratios used in cutting a mould segment for one particular type of worm wheel. Worm and worm wheel data: 94/1 ratio (4 threads on worm and 37 teeth on wheel), 8.625" C.D., 14.002" P.D. of wheel, 1.2315" C.P. of 115 wheel, 4.926" lead; slider (46) and worm (25) data: 117/1 ratio (1 thread on worm and 117 teeth on slider for 360°), 5.0" D.P.; 23.4" P.D. of slider, 0.6283" lead; sector (88) data: 16 D.P., 256 teeth in 360°; gear 120 (76) data: 20 teeth; gears (82) and (87) data: proper number of teeth to set up drive between sector 88 and gear 76. From an inspection of Fig. 6, it will be seen that the angular length of the tooth contours of 125 mould segment B about the axis WO is substantially 90°. With the above-mentioned ratios, the blank will be moved 1.2315" about the axis WH (as measured

90.

10

on the pitch radius) for a 90° rotation about the axis WO.

A typical, so-called tin-rich bronze employed in casting a worm wheel in a mould constructed in accordance with the invention is designated S.A.E. \$65, and has 89% copper and 11% tin content. This is a bearing alloy possessing ideal metallurgical properties for a worm wheel.

The manner in which the cutter or tool T is mounted will be described in connection with Figs. 11 and 12. The cutter may be mounted in any convenient manner; however, it is preferred that the mounting arrangement provide for the rotational axis of the cutter to lie in the axial plane of the worm wheel and of the mould segment B. Also, it is preferable that the cutter be angularly adjustable in said plane. While Figs. 11 and 12 show a typical mounting arrangement for the cutter for use with a horizontal-type milling machine, it will be understood that a vertical-type machine can be used.

The horizontal supporting bar 140 of the machine has two depending bracket straps 141 and 142 secured thereto. As indicated in Fig. 11, the straps are provided with slots 143, and by tightening up on the 30 nut and bolt assemblies 144, the straps may be held fixed on the bar. A generally cylindrical housing 145 is disposed between straps 141, 142, to which is secured the cutter T. Each strap is provided with a plurality of arcuate slots 146 through which extend screws 147 threaded in the housing 145 as indicated in Fig. 12. As will be apparent if the screws 147—147 are loosened, the housing, hence the cutter T, can be angularly adjusted.

In order to mount the cutter in the housing 145 (Fig. 12) the housing has a vertical aperture and the cutter spindle 148 extends therethrough. Near the top, combination axial and radial thrust bearings 149 are mounted on a ledge 150 in the housing 145 and operate to rotatably support the spindle. A bearing retainer 151 engages a flat portion 152 of the housing 145, being secured 50 thereto as by screws 153. A nut 154 is screwed on the spindle 148 and is pulled up against a spacer 155 which abuts bearings An oil seal 156 is disposed interjacent the spacer and the bearing retainer. On a flat portion 157 on the bottom of the housing 145 is mounted a bearing retainer 158, which is secured thereto by screws 159. Combination axial-radial thrust bearings 160 support the spindle 148 and are mounted on a ledge 161 on the bearing retainer 158, bearing against a ledge 162 on the housing 145. An oil seal 1591 is disposed around the spindle 148 shaft adiacent the bearing retainer 158. The spindle shaft 1481 is rotated by a bevel gear 163

secured to the shaft as by key 164. A sleeve 165 is mounted over the shaft interjacent the bevel gear 163 and the bearings 149.

The cutter is held fast on the spindle by means of the draw bar 166 which extends through an aperture in the spindle shaft 148¹ and is pulled up tight by means of a nut 167 threaded on the upper end of the draw bar.

70

75

85

90

The bevel gear 163 meshes with a driving bevel gear 168 disposed within a bushing 169 held in the housing 145 by the bracket strap 141; and the bevel gear 168 is keyed to a drive shaft 170 by the key 171. The same key also connects the spacer sleeve 172 to the shaft, the spacer extending out to the milling machine so as to provide a bearing for the gear and being rotatable within the bushing 173. A nut 174 is threaded on the end of shaft 170 to hold the bevel gear 168 in axial position. The drive shaft 170 is connected to mechanism in the milling machine which provides for rotation thereof.

The manner in which the machine is operated to cut blanks into mould segments will next be described.

First, a plurality of segmental blanks B which will go to make up the ultimate mould are produced by sawing segments of the dotted-line outline l (Fig. 1) from a continuous circular blank casting (not shown) which has the same radial cross sectional proportions as the sawed mould section B. 100 Fig. 14 shows a plurality of these segments arranged together in the form of a ring-like composite mould, the mould cavities being designated MC.

The radial dimensions and sectional 105 dimensions of the ring casting are such that following the sawing of a mould segment B therefrom and the machining of teeth therein by the structure above described, a worm wheel chill cast against a mould composed 110 of such machined segments will have the desired dimensions in regard to its diameter. width and tooth proportions. A number of mould segments B sufficient to make up a composite 360° annular mould are then 115 machined from these rings, the ends of each blank being cut radially and on a predetermined face-to-face or top to bottom bias such as is indicated by the numeral 175 in Figs. 1, 2 and 14. The index holes 49 and 120 51 are accurately located with respect to the ends. From an inspection of Figs. 1 and 2, it will be apparent that the top portion of the blank B (as indicated by the dotted lines l) is generally concave (as viewed from 125 axis WH) and that the various mould cavities or mould contours which are cut therein are generally convex with respect to the concave portion as viewed from the same position. 130

In machining the top portion of the blank and in cutting the various mould contours, casting shrinkage factors are taken into account. This is done on the basis of radial shrinkage, i.e., assuming that the casting shrinks toward the center. The composite mould is oversize, so to speak, so that as the molten metal contracts on cooling, the wheel will be within desired tolerances. With bronze i.e., the tin-rich bronze described above, the usual shrinkage allowance is $^{1}/_{64}$ " per inch. Thus, for the casting of, say, a 12" diameter wheel, the segments are made as if the wheel were $12^{3}/_{16}$ diameter. The outer surface of the top portion of the blank is machined so that as the casting cools, the portion r will correctly form the root of the teeth. Also, as noted later, the cutter is maintained in cutting por-20 tion t at a predetermined distance from the axis WO so that as the casting cools, the throats on the wheel are correct. shrinkage allowance for r and t automatically compensates for the shrinkage of the contours, although allowance for this may be provided in some instances.

There are several alternative ways of operating the machine to form the mould cavities. For example, the mould contours or lead contours C1, C2, etc., can be sequentially formed on a first blank and then the other blanks making up the composite mould are sequentially inserted into the machine and the corresponding mould contours formed thereon. Then the original blank can be again set up in the machine and the contours C11, C21, etc., formed. A similar operation is sequentially performed on the remainder of the blanks. tively, the segments can be completed one at a time. For example, the contours C1, C2, etc., can be formed on the first blank. Or the contours on either side of a mould body can be formed (such as C1 or C2) and then the mould contour on the other side of the mould body (C2 or C1) can be formed and then the mould contours on the next mould body formed, etc. It will be apparend that other ways to form the cavities are available with the machine but in any event, it is preferred that the procedure requiring the least number of adjustments to make all of the segments for the composite mould be adopted. The preferred methods will be 55 explained shortly but it is desired first to comment on the arrangement of the cutter.

Ordinarily, the cutter is angularly adjusted by means of housing 145 in the axial plane so that the rotational axis is offset from the mutual perpendicular of the two axes WH and WO. The general effects of offsetting will be later described.

One effect is to enable the machine to form the desired contours or lead contours on 65 the blank to correspond to the desired lead contours of the teeth of a wheel to be used with a cylindrical worm or to correspond to teeth on a wheel for use with a double enveloping worm. Exact tooth form for such wheels may vary depending upon such factors as load, speed and other known factors. In a typical tooth for use with a double enveloping worm, the tooth may be thickest at the center and thinnest at the outer edges. the decrease in thickness being symmetrical about the center. In a typical tooth for use with a cylindrical worm, the tooth may be thinnest at the center and thickest at the outer edges, the increasing thickness being symmetrical about the center.

75

110

A wheel having teeth for use with a cylindrical worm will be termed hereinafter a "cylindrical wheel" and a wheel having teeth for use with a double enveloping worm will be termed a "double enveloping wheel".

Ordinarily, the pressure angle contour of a tooth on a double enveloping wheel is straight, i.e., in cross section the shape of a tooth is generally in the form of a truncated triangle. Thus, for forming contours in a blank for casting this type of tooth, the cutter is generally conical in shape so that the cutting edge is straight. The pressure angle contour of a tooth on a cylindrical wheel is generally curved or involute in form and the cutter used is semispherical, so to speak, i.e., so that the cutting edge is inversely curved or involute.

The rotational axis of the cutter is 100 ordinarily positioned either to the left or right side (as viewed in Figs. 1 and 2) of the mutual perpendicular of axes WO and WH. In either case, for cutting the contours for a double enveloping wheel, the 105 side or edge of the cutter farthest from the mutual perpendicular is used, while in cutting the contours for a cylindrical wheel, the side or edge of the cutter nearest the mutual perpendicular is used.

The following example will illustrate the foregoing. For a tooth for a double enveloping wheel the rotational axis of the cutter may be oriented to the left of the mutual perpendicular (as viewed in Fig. 2) 115 and the edge indicated at 180 used. For a tooth for a cylindrical wheel the edge 180¹ would be used.

The other effect of offsetting the cutter is in the formation of the pressure angle 120 or pressure contour of the tooth to be cast. This will be apparent from an inspection of Fig. 1a where (assuming the mould cavity MC is the tooth of a wheel) the pressure angle is indicated at PA, i.e., the angle be- 125 tween the tangent 181 to the pitch line and the normal 182 to the contour. By tilting the cutter, the pressure angle or contour may be changed. Further, it will be apparent that the pressure angle may be deter- 130

BNSDOCID: <GB 871020A | > mined or effected by the particular shape of

The lead and pressure angle contours of the teeth of the wheel to be cast can be obtained by the selection of the amount of offset and the shape of the cutter.

With the above in mind, we return now to an explanation of the preferred methods

of the invention. Having constructed several blanks for the composite mould and arranged the gear ratios (both in accordance with the Specifications of the wheel to be cast), the machine must be set up so that the contours 15 cut will give the desired tooth shape in the casting. This involves the shape of the cutter and the offset of its rotational axis

from the mutual perpendicular.

The particular shape and offset of the cutter can be calculated from the known pressure angle and lead contour of the teeth of the desired wheel and then the cutter offset by locating the axis relative to some known point on the machine. However, for most foundry purposes, the wheel to be cast will be a duplicate of a wheel already. made, say for example, by known hobbing methods. Thus, the machine of the invention can be set up by using a master segment made from such a wheel.

The master segment is usually made from an arcuate wooden blank having the same cross sectional shape as the lower portion 41 of the segments. This is placed at the proper distance from the center of the wheel to be duplicated and plaster poured interjacent the blank and the wheel teeth. Thus, the blank is provided with a plaster section having the impression of the teeth on the wheel. A locating hole (corresponding to index hole 49) is machined in the master. While this hole must be located so that when the master is placed on the cradle it will line up with any of holes 47-47 on the slider. it is not too important where the hole is located along the arcuate length of the master. Preferably the hole should be between two adjacent impressions.

The milling machine table is then operated to move the cradle downwardly away from the cutter and the master mounted on the cradle and the pin 50 inserted in the hole 47a and in the locating hole in the master. The machine is then operated to arrange the cradle symmetrically about the

axial plane, i.e., as shown in Fig. 6.

The cutter is then arranged so that its rotational axis is vertical and the table moved horizontally so that the mutual perpendicular of the axes WH and WO and the rotational axis of the cutter are coaxial. This locating can be done by conventional shop methods. The table is then moved upwardly and the cutter axis is offset so that the cutting edge of the cutter lies along

the pressure angle contour of a mould body on the master and so that the bottom of the cutter abuts the throat (corresponding to throats t-t in Fig. 1a). The particular mould body and contour thereof selected depends upon the type of tooth to be cast and whether the cutter is to be offset to the right or left-hand side of the mutual perpendicular. It is pointed out that the foregoing adjustment may require some side feeding of the master. Incidentally, it should be observed that side feeding is always done with the cradle arranged symmetrically about the axial plane; this, of course, sets up the master, blank or segment (whichever is mounted in the cradle) symmetrical with respect to the axial plane.

After the above is completed, the machine is made to operate, preferably by hand, so that the two simultaneous motions about the axes WO and WH are imparted to the master. The position of the cutter along the lead contour is observed during this motion. If the lead contour of the master pulls away or goes into the cutting edge, the machine is operated to place the master back in the axial plane and then a little more offset is given to the cutter and/ or the machine is side fed to bring the cutting edge up to the pressure angle contour. Further, the table may have to be raised to bring the lower end of the cutter abutting the throat. The machine is then put through the simultaneous motions to see that the lead contour follows the cutting edge.

After the above-described adjustments are correctly made, the machine is set up to cut the mould cavities on the blanks. The table-lifting mechanism on the milling machine can then be marked so that when the 105 table is lowered, it can subsequently be raised to the correct throat position. The raised to the correct throat position. shrinkage factor for the throats can be set

into this position. The milling machine table is then lowered 110 and the master segment removed and a blank inserted in the cradle by inserting the pin 50 in the hole 47a and the hole 49 (or 51). The milling machine table is then moved upwardly to the throat position and 115 the machine operated to impart the simultaneous motions to the blank to put the same in the axial plane. Ordinarily, the end of

the blank will be somewhat spaced (along the axis WO) from the cutter. The cutter 120 is then turned on and the blanks side fed into the cutter a sufficient depth so that enough metal is available for forming all of the desired contour.

The milling machine table is then lowered 125 and the machine is operated to impart the simultaneous motions and the blank is put in position for the contour forming operation. Preferably this is with the blank rotated to a clockwise position (Fig. 6) 130

BNSDOCID: <GB__ _871020A__l_>

85

where the edge 177 (Fig. 1) is about in the position of the dotted line 1771 (Fig. 6). The table is then raised to the throat position and then the machine operated so that the simultaneous motions are imparted to the blank and the first contour, say, the contour

corresponding to C1, is formed.

The table of the milling machine is then lowered away from the cutter and the blank 10 indexed. This is done by taking out pin 50, moving the blank so that its hole 49 (or 51) is lined up with the hole (47) in the slider adjacent hole 47a and then re-inserting the pin. The machine is then operated for simultaneous movement of the blank to contour cutting position. The machine is operated to cut the next contour, say, C2. The above procedure is then followed for the remaining contours, say C3 and C4.

The next adjacent blank making up the composite mould is inserted in the cradle and contours corresponding to C1, C2, etc., are cut. The remaining blanks are then sequentially operated on to cut the corresponding contours. After all of the blanks have been so worked, the first blank is then reinserted in the cradle but turned 180°, i.e., end-for-end. With the table at the correct throat position, a rough cut can be made close to the ultimate position of contour C12 and then the blank side fed so that the contour C11 is located or spaced the correct amount from the contour C1. After this adjustment has been made, the machine is operated so that the contours corresponding to C11, C21 etc., are formed. The remaining blanks are taken in order and the corresponding contours formed therein.

The above-described method for forming 40 the mould cavities is preferred because the chance of error is minimized. The bias on the edges and the index holes are very accurately located with respect to one another and the same accuracy is maintained as between blanks. Once the first contour C1 on the first blank has been cut, the accurate machining of the blanks and the indexing arrangement automatically insures that all of the corresponding contours around the 50 mould will have the correct spacing. same holds true after the contour C11 is correctly spaced from C1.

Instead of sequentially forming the contours corresponding to C1, C2, etc., on all of the blanks making up the mould, the same contours can be formed on a single blank and then that blank set up end-forend in the machine and the contours corresponding to C1¹, C2¹, etc., be formed. Similar operations can be made on the remaining blanks

Also, it will be apparent that when the contours corresponding to C1, C2, etc., have been formed on a blank, the contours corresponding to C11, C21, etc., can be

formed by leaving the blank in its initial position on the cradle and arranging the cutter to occupy a mirror image position on the opposite side of the mutual perpendicular.

It is pointed out that in operating the machine for making any of the contours as above-described, the cut is taken in the same direction. In other words, the direction of movement of the blank with respect to the cutter should always be the same when a contour is being formed. On this manner, the effect of back-lash in the various gear trains is eliminated. Further, it is mentioned that the cradle may, it it is desired, be provided with appropriate counterweights so as to provide a balancing of the mass about the axis WO.

With the above-described methods, worm wheels can be cast with teeth so precise in dimension that a wheel merely has to be run in or possibly lapped to be suitable for its intended purpose. Indeed, the wheels may be used directly as cast, particularly where lead is added to the bronze to get desired lubricating properties. In some instances, where the particular application of the wheel requires, the wheel may be cast with the teeth somewhat oversized in order to leave metal for a subsequent machining or hobbing operation. It is contemplated however, that the machining of the mould blank segments shall afford a desired slight oversize as to the tooth contours of the completed mould segment, so that shrinkage 100 after moulding against these contours will result in a worm wheel proportioned exactly as desired after removal from the composite, multi-segment mould.

A precision worm wheel produced in 105 accordance with the above described method forms the subject of Patent Application No. 14988/60 (Serial No. 871,021).

WHAT I CLAIM IS:-

1. Apparatus for use in forming mould 110 cavities in a mould blank for casting a worm wheel, including a support for mounting said blank; first means for arcuately moving said support about a first axis corresponding to the rotational axis of a worm 115 with which the wheel to be manufactured is to be used; second means for arcuately moving said blank mounted on said support, about a second axis corresponding to the rotational axis of the wheel to be cast; 120 and mechanism providing for simultaneous operation of said first and second means, the arrangement being such that said blank can be moved as aforesaid against cutting means to form said cavities.

2. Apparatus as claimed in Claim 1. wherein said mechanism is such that said second means can be operated while said first means is inoperative.

3. Apparatus as claimed in Claim 1 or 2, wherein a cradle is connected to a base so as to be arcuately movable about said first axis, said support being on said cradle and providing for said movement of the blank about said second axis, said mechanism having drive means for simultaneously moving said cradle and said blank.

4. Apparatus as claimed in Claim 3, wherein said cradle is disposed between two supporting brackets and has a curved face for supporting said blank, a slider mounted on said cradle being engageable with said blank for moving said blank along said surface, bearing means being arranged to support rotatably one end of the cradle and one of said brackets, a first shaft connected to the other end of the cradle being rotatably supported by the other of said brackets, there being a second shaft rotatably supported by said cradle and driving connections between said second shaft and said slider, said first and second shafts being interconnected for simultaneous operation thereof.

5. Apparatus as claimed in Claim 4, wherein said curved face is presented by an adapter screwed onto the cradle, said face having an axis which is coaxial with an axis corresponding to the rotational axis of the wheel to be manufactured, said first and second shafts being interconnected by a strap, there being a gear bracket fixed to said strap, a first gear fixed on said second shaft, and a fixedly mounted gear sector connected to said first gear by gear means mounted on said bracket.

6. Apparatus as claimed in any one of Claims 1 to 5, wherein a rotary cutter constituting said cutting means has the rotational axis thereof arranged generally in a plane containing said first axis, the cutter being arcuately adjustable in said plane about said second axis.

45 7. A method of manufacturing a mould for casting a worm wheel, including the steps of forming a plurality of arcuate mould segments constituting mould blanks, forming mould cavities on the concave inner surfaces of the individual segments with the aid of apparatus as claimed in any one of Claims 1 to 6, so as to provide mould contours in said segments which are convex transversely of the latter and are complementary to the teeth of the worm wheel to be manufactured; and assembling said segments to form a continuous annular mould having said contours on the inner surface thereof.

8. A method as claimed in Claim 7, wherein said arcuate mould segments are formed by cutting said segments from a circular mould blank.

9. A method as claimed in Claim 8, wherein the cutting of said circular mould blank to form said segments is performed in planes inclined with respect to radial planes through the axis of the blank.

65

70

75

85

10. A method as claimed in Claim 7, 8 or 9, wherein the formation of said mould cavities is controlled so as to produce tooth contours on the mould segment of such oversize with respect to the teeth of the wheel to be manufactured, that molten metal having shrunk after being cast against said contours will have the precise dimensions and contour of said teeth.

11. A method as claimed in any one of Claims 7 to 10, wherein said tooth cutting operation is effected by causing a cutting engagement of a tool with said inner surface in a compound relative movement including an angular component about the axis of said arcuate mould and a rocking component about an axis disposed radially outwardly of said surface.

12. A method as claimed in Claim 11, wherein said movement is defined as the resultant of two simultaneous arcuate movements, one described by an arc having its centre lying in a first axis corresponding to the rotational axis of the worm with which the wheel to be manufactured is to be used, whereby said contour is generally convex with respect to said inner surface, and the other described by an arc having its centre lying in a second axis corresponding to the rotational axis of the wheel to be cast.

A method as claimed in Claim 12, including the steps of maintaining a rotary 100 cutter constituting said tool in a known relative position with respect to said first axis, orienting said segment which segment is generally elongated, whereby a preselected portion thereof occupies a known relative 105 position with respect to said cutter, the longitudinal axis of the segment lying in a plane containing said first axis; forming one side of a mould cavity to be formed by starting from said known position and engaging 110 the blank with the cutter, the engagement being effected by causing the blank to move relative to the cutter to effect said relative movement.


14. A mould when produced by the 115 method claimed in any one of Claims 7 to 13, having a radially inner matrix portion having parallel axially convex tooth contours on the inner surface thereof which contours are of the axial width of the wheel to 120 be manufactured.


Apparatus for use in forming mould cavities in a mould blank for casting a worm


wheel, substantially as hereinbefore described with reference to Figures 1 to 14 of the accompanying drawings.


16. A method of manufacturing a mould 5 for casting a worm wheel, substantially as hereinbefore described with reference to the accompanying drawings. HASELTINE, LAKE & CO., Chartered Patent Agents, 28 Southampton Buildings, Chancery Lane, London, W.C.2, Agents for the Applicant.

Abingdon: Printed for Her Majesty's Stationery Office, by Burgess & Son (Abingdon), Ltd.—1961.
Published at The Patent Office, 25, Southampton Buildings, London, W.C.2,
from which copies may be obtained.











871,020 COMPLETE SPECIFICATION
4 SHEETS This drawing is a reproduction of the Original on a reduced scale.

SHEET 2



871,020 COMPLETE SPECIFICATION 4 SHEETS This drowing is a reproduction of This drawing is a reproduction of the Original on a reduced scale.
SHEET 2 ol 8 Ħ Jeg. 6. Z Fig. 10

100 100 BM K



871,020 4 SHEETS COMPLETE SPECIFICATION

This drawing is a reproduction of the Original on a reduced scale. SHEETS 3 & 4








FIG.15. Seg. 12. 9

871,020 COMPLETE SPECIFICATION 4 SHEETS This drawing is a reproduction of the Original on a reduced scale. SHEETS 3 & 4











871,020 C 4 SHEETS 71

COMPLETE SPECIFICATION

This drawing is a reproduction of the Original on a reduced scale.
SHRET 2



871,020 COMPLETE SPECIFICATION
4 SMEID 165 dening to englateine of
the Original or endand unit, * Ų, Sep. 10



871,020 COMPLETE SPECIFICATION
4 SHEETS This drawing is a reproduction of the Original on a reduced scale.
SHEETS 3 & 4




FIG.15. Ė ST AND 뛲

4 SPEETS THE STRUCKETE SPECIFICATION 4 SPEETS THE SHOWING IN a Reymology of the Conjust of the transport of the Speed with SPEETS 8 & 4

THE BYCE BLYNK (USPTO)

I,